

# MEMORANDUM

DEPARTMENT OF TRANSPORTATION  
Staff Bridge Design  
4201 E. Arkansas Avenue, Room 330  
Denver, Colorado 80222  
(303) 757-9309 FAX (303) 757-9197



Date: April 10, 2000

To: All Bridge Design Manual Users

From: S. W. Horton, Bridge Branch Manager

Subject: CDOT Bridge Design Manual Revisions

The following subsections of the CDOT Bridge Design Manual have been updated:

- Table of Contents
- Revision Log
- 17.2 Utility Blockouts
- 19.1 Minimum Requirements for Major Structures
- 19.5 Overlays

These subsections are available electronically through the CDOT bridge web page.

<http://www.dot.state.co.us/business/Design/Bridge/index.htm>

Structural personnel should review and become familiar with these revisions. If you have any questions or recommendations for improvement please contact:

[mark.leonard@dot.state.co.us](mailto:mark.leonard@dot.state.co.us) 757-9486

[Prabhatsinh.Padhiar@dot.state.co.us](mailto:Prabhatsinh.Padhiar@dot.state.co.us) 757-9370

SWH/PKP/MAL/mal

Distribution via e-mail:

Reisbeck	Program Engineers
Unbewust	Resident Engineers
Talmdage	Staff Bridge Employees
Greer, FHWA	Structural Consultants
Branch Managers	